



USED MACHINE INSPECTION REPORT PAVER

1. General Information

Machine Model	SUMITOMO HAGOC-7	Serial No.	SMTAGOK3VD0000042
Year	2013	Operating Hours	
Screed	SP2360	Screed No.	//
Paving Width	2,3 - 6 m	Screed Extensions	//
Levelling System / Make / Type	MOBA Matic CAN1	Levelling System Configuration	2x Semic SK; 1x Dig. Rotary
Customer		Date, Location	15-06-23/POLAND

2. Equipped with following Options

Sun roof	<input checked="" type="checkbox"/>	Side curtains	<input type="checkbox"/>	Cabin	<input type="checkbox"/>
Working lights	<input checked="" type="checkbox"/>	Additional working lights	<input type="checkbox"/>	Warning beacon	<input type="checkbox"/>
Screed lock	<input checked="" type="checkbox"/>	Screed anti-climbing lock	<input type="checkbox"/>	Spacer blocks, screed	<input type="checkbox"/>
Screed Diesel heating	<input type="checkbox"/>	Screed gas heating	<input checked="" type="checkbox"/>	Electric heating, screed	<input type="checkbox"/>
ThermoControl	<input checked="" type="checkbox"/>	Tropicalised	<input type="checkbox"/>	Sound insulation	<input type="checkbox"/>
Central lube, paver	<input checked="" type="checkbox"/>	Central lube, screed	<input type="checkbox"/>	Automatic steering	<input type="checkbox"/>
Diesel transfer pump	<input type="checkbox"/>	Emulsion tank	<input type="checkbox"/>	Screed tensioning device	<input type="checkbox"/>
2 Limit switches or USS for the auger	<input checked="" type="checkbox"/>	Screed load device	<input type="checkbox"/>	Other options	<input type="checkbox"/>

3. CE Conformity of the Machine:

	yes	no	s. below
The has already been in free circulation within the European Union (i.e. a CE label is affixed on the machine).	X		a)
No alterations have been made on the machine (e.g. increase of output, alteration of the functions and safety devices etc.).	X		
If the previous question was answered with "no", a risk analysis must be made:			
Have any new or additional safety risks arisen ? (If so, specify the reason under item 4)		X	b)

a) If the answer is no, the used machine must not be sold within the European Union.

b) If the answer is yes the used machine must not be sold within the European Union.

In both cases there is no CE conformity for the machine.

Machine is CE conform: yes, non (not for resale in the European Union)

Operating instructions with machine: no yes, Qty: , Language:

Spare parts lists with machine: no yes, Qty: , Language:

Place, Date, Name/Signature

Poland 15-06-23 Pado Bressan

Please Note: If this Used Machinery Inspection Report is not properly completed, the machine cannot be correctly assessed and unnecessary costs will arise.

MACHINE PARTS SERVICE



4. Assemblies and Components

Assess the condition of the assemblies and components using a scale of 1 – 5 :
5 = as new, 4 = good, 3 = average, 2 = below average, 1 = poor

	Condition (1 - 5)	Remarks (mm / %)
Appearance		
1 Paint work	3	
2 Superstructure	4	
3 Frame and welding work	5	
4 Control panel / instruments (EPM/AGB)	4	
5 Seat with console	4	
6 Hopper wings, hinges & hinge rods	4	
Conveyor System		
7 Hopper floor plates (mm)		7 mm
8 Conveyor chain covers (%)		80%
9 Chains / shafts / gear wheels (%)		80%
10 Drive chains		70%
11 Hoses central lubrication	3	
Undercarriage		
12 Track plates / tyres (%)		100%
13 Track gear wheels (%)		80%
14 Track rollers / Track tensioners		80%
Augers		
15 Flights, bearing protectors and shafts (%)		80%
16 Auger drive case		80%
17 Centre auger drive		80%
18 Outer auger drive		80%
19 Outer auger bearings		80%

	Condition (1 - 5)	Remarks (mm / %)
Electrics / Lev. System / Drive/ Engine		
20 Cable looms, switches etc.	4	
21 Battery	5	
22 Grade control	4	
23 Slope control		
24 RSS, Big Ski or similar system	//	
25 Diesel engine	5	
26 Pump distributor gear	//	
27 Hydraulic pumps	5	
28 Hydraulic motors	5	
29 Valves, valve blocks	5	
30 Steering	5	
31 Brakes, parking brake	5	
32 Hoses, tubing (paver)	4	
Screed		
33 Base plates (mm)		9 mm
34 Tamper bars (%)	80%	
35 Shafts, bearings, lube system	80%	
36 Vibrator shafts, bearings	80%	
37 Hydraulic motors	80%	
38 Vario cylinders, cylinder guides	80%	
39 Hoses, tubing	80%	
40 Gas / Gas Heating	80%	
41 Electric heating	//	

5. General comments on the machine:

Machine in Excellent condition ready for working

Special design:

(This assessment is valid for 1 month or 100 hours. Thereafter a new assessment is required).

Trade-in Price EUR _____

Date, Name/Signature

MACHINE PARTS SERVICE

