



USED MACHINE INSPECTION REPORT PAVER

1. General Information

Machine Model	VOLVO ABG6870	Serial No.	77003
Year	2010	Operating Hours	7752
Screed	VB781 ETC	Screed No.	200045
Paving Width	2,5 - 5,0 m	Screed Extensions	No
Levelling System / Make / Type	TOBA Matic PWM	Levelling System Configuration	2x Toba Matic 2x Sarnic Ski 1x Slope sensor
Customer		Date, Location	

2. Equipped with following Options

Sun roof	<input checked="" type="checkbox"/>	Side curtains	<input type="checkbox"/>	Cabin	<input type="checkbox"/>
Working lights	<input checked="" type="checkbox"/>	Additional working lights	<input type="checkbox"/>	Warning beacon	<input checked="" type="checkbox"/>
Screed lock	<input checked="" type="checkbox"/>	Screed anti-climbing lock	<input type="checkbox"/>	Spacer blocks, screed	<input type="checkbox"/>
Screed Diesel heating	<input type="checkbox"/>	Screed gas heating	<input type="checkbox"/>	Electric heating, screed	<input checked="" type="checkbox"/>
ThermoControl	<input checked="" type="checkbox"/>	Tropicalised	<input type="checkbox"/>	Sound insulation	<input type="checkbox"/>
Central lube, paver	<input checked="" type="checkbox"/>	Central lube, screed	<input type="checkbox"/>	Automatic steering	<input type="checkbox"/>
Diesel transfer pump	<input type="checkbox"/>	Emulsion tank	<input type="checkbox"/>	Screed tensioning device	<input type="checkbox"/>
2 Limit switches or USS for the auger	<input checked="" type="checkbox"/>	Screed load device	<input type="checkbox"/>	Other options	<input type="checkbox"/>

3. CE Conformity of the Machine:

	yes	no	s. below
The has already been in free circulation within the European Union (i.e. a CE label is affixed on the machine).	<input checked="" type="checkbox"/>	<input type="checkbox"/>	a)
No alterations have been made on the machine (e.g. increase of output, alteration of the functions and safety devices etc.).	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
If the previous question was answered with "no", a risk analysis must be made:			
Have any new or additional safety risks arisen ? (If so, specify the reason under item 4)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	b)

a) If the answer is no, the used machine must not be sold within the European Union.

b) If the answer is yes the used machine must not be sold within the European Union.

In both cases there is no CE conformity for the machine.

Machine is CE conform: yes, non (not for resale in the European Union)

Operating instructions with machine: no yes, Qty: , Language: IT

Spare parts lists with machine: no yes, Qty: , Language: IT

Place, Date, Name/Signature

Arconate, 22-06-23 Paolo Bressan

Please Note: If this Used Machinery Inspection Report is not properly completed, the machine cannot be correctly assessed and unnecessary costs will arise.

MACHINE PARTS SERVICE



O.M.S.s.r.l - Sede Legale e Amministrativa:

20020 Arconate (MI) ITALY - Via G. Rossa, 16 - Tel.: +39 0331 462350 - Fax: +39 0331 539391- info@ombsbressan.it - www.ombsbressan.com
Capitale Sociale €30.000,00 i.v. - Cod.Fisc. e P. IVA e Reg. Imp. IT 09956980156 - CCIAA MI 1327815

4. Assemblies and Components

Assess the condition of the assemblies and components using a scale of 1 – 5 :

5 = as new, 4 = good, 3 = average, 2 = below average, 1 = poor

	Condition (1 - 5)	Remarks (mm / %)
Appearance		
1 Paint work	4	
2 Superstructure	4	
3 Frame and welding work	5	
4 Control panel / instruments (EPM/ASS)	5	
5 Seat with console	5	
6 Hopper wings, hinges & hinge rods	5	
Conveyor System		
7 Hopper floor plates (mm)		70%
8 Conveyor chain covers (%)		70%
9 Chains / shafts / gear wheels (%)		70%
10 Drive chains		70%
11 Hoses central lubrication		
Undercarriage		
12 Track plates / tyres (%)		50%
13 Track gear wheels (%)		
14 Track rollers / Track tensioners / <i>Front Wheels</i>		50%
Augers		
15 Flights, bearing protectors and shafts (%)		
16 Auger drive case		80%
17 Centre auger drive		80%
18 Outer auger drive		80%
19 Outer auger bearings		80%

	Condition (1 - 5)	Remarks (mm / %)
Electrics / Lev. System / Drive/ Engine		
20 Cable looms, switches etc.	5	
21 Battery	5	
22 Grade control	4	
23 Slope control	4	
24 RSS, Big Ski or similar system	//	
25 Diesel engine	5	
26 Pump distributor gear	5	
27 Hydraulic pumps	5	
28 Hydraulic motors	5	
29 Valves, valve blocks	4	
30 Steering	5	
31 Brakes, parking brake	5	
32 Hoses, tubing (paver)	4	
Screed		
33 Base plates (mm)		4
34 Tamper bars (%)		70%
35 Shafts, bearings, lube system		90%
36 Vibrator shafts, bearings		90%
37 Hydraulic motors		90%
38 Vario cylinders, cylinder guides		80%
39 Hoses, tubing		80%
40 Gas / Diesel heating	//	
41 Electric heating		50%

5. General comments on the machine:

Special design:

(This assessment is valid for 1 month or 100 hours. Thereafter a new assessment is required).

Trade-in Price EUR _____

23-06-23, *P. de Bressa*
Date, Name/Signature

MACHINE PARTS SERVICE

